



LEVELTON ASSOCIATES CONSULTING ENGINEERS

RICHMOND

VICTORIA

NANAIMO

COURTENAY

SURREY

ABBOTSFORD

PRINCE RUPERT

November 18, 1993

File No. 293-020

Hastings Brass Foundry Ltd.
236 Clark Drive
Vancouver, B.C.
V5L 3H3

ATTENTION: Mr. Dave Esworthy

RE: Pressure testing of 2 1/2" Hydrant Gate Valve for P.O. # 006175

Dear Mr. Esworthy;

As requested, B.H. Levelton & Assoc. Ltd. performed a Hydrostatic Pressure Test of the submitted 2 1/2" Hydrant Gate Valve. The assembly was filled with water then pressurized with the use of an hydraulic pump. The maximum pressure obtained was 1500 Psi. The hydrant gate was closed during the test. Failure occurred in the rubber O - Ring between the gate valve body and the brass nipple.

We trust this information is satisfactory for your present requirements. Please call if you have any questions or comments regarding this matter.

Yours truly,

B.H. LEVELTON & ASSOCIATES LTD.

L.A. Gibson, Tech.